

It is noted that the specification describes two different "longitudinal" lines, one of which is the longitudinal axis of the spool, and the other is a line connecting the end zones of the slot. It appears that the error in the claim arose due to confusion between the two different longitudinal lines.

Examination of amended claim 1 and claims 2-6 which depend therefrom is respectfully requested.

Respectfully submitted,

BACON & THOMAS, PLLC



By: BENJAMIN E. URCIA
Registration No. 33,805

Date: December 1, 2000

BACON & THOMAS, PLLC
625 Slaters Lane, 4th Floor
Alexandria, Virginia 22314

Telephone: (703) 683-0500

NWB:S:\Producer\beu\Pending A...H\B\baumgartner reissue\reissue AMENDMENT.wpd